
1188 Commonwealth Avenue, Boston



#### **Project Team**

Owner: The Herb Chambers Companies
Architect: Mark Regent, Regent Associates, Inc.

Permitting Attorney: Don Wiest, Dain | Torpy

Corporate Council: Paul Losordo
Civil Engineer: Gabe Crocker, CHA

Traffic Consultant: Jeff Dirk, Vanasse & Associates

LEED Consultant: Jay Murray, C3
Landscape Architect: Clara Batchelor, CBA

1188 Commonwealth Avenue, Boston

Where we started, based on Jaguar Land Rover's new ARCH image guidelines...

#### **Initial Comments:**

"It's too boxy and horizontal, while everything else in the area is a smaller scale and more vertical".

"Maybe extend the portion above the front entrance to the roof line to create more of a separation between the two sides, add a canopy over the doors to highlight the entrance."

"It's a 'big box without any interesting or distinguishing architectural elements'...".

"...surprised Chambers and Jaguar/Land Rover wanted to build a "flagship downtown dealership with such a boring, industrial looking design".

"The Service Entrance is set back too far with a parking lot between this and Porsche."





1188 Commonwealth Avenue, Boston


Comment: "There are better looking JLR dealerships that are more interesting..."



Very few **multi-story**, JLR-compliant dealerships have been built in **urban** locations. None we have found are located in a mostly residential urban neighborhood.







1188 Commonwealth Avenue, Boston

Comment: "Look at the evolution of the site. Look at the street. Do a typological analysis of the street including the BMW/Mini buildings. You have three brands, three buildings, three scales and lots of parking."



This section of Commonwealth Avenue has had automotive dealerships for nearly 100 years. Cars are big, and with the current situation, they cannot be 'hidden' inside the buildings. We are trying to rectify this by including a vehicle storage facility inside.

1188 Commonwealth Avenue, Boston

Comment: "Look along the street to the east and across the street where you see long stretches of very regular articulation."



1130 - 1150 Commonwealth Avenue



1188 Commonwealth Avenue, Boston

Comment: "Look along the street to the east and across the street where you see long stretches of very regular articulation."



Directly west of the site - 1200 Commonwealth Avenue to Harvard Avenue



Directly across Commonwealth Avenue




1188 Commonwealth Avenue, Boston

Comment: Look along the street to the east and across the street where you see long stretches of very regular articulation.

#### Scale

While the scale may be slightly different between the residential buildings to the east, proportionately they are very similar. This is supplemented by the spacing of the vehicles and lighting compared to the smaller scale elements of the residences. Further, changing the upper level to be mostly glass creates a virtual cornice, reflecting those along the residential blocks.




1188 Commonwealth Avenue, Boston


#### Commonwealth Avenue Improvement Project



1188 Commonwealth Avenue, Boston


#### Commonwealth Avenue Improvement Project





We understand that the DPW has plans in the works to widen sidewalks, eliminate the current parallel parking, add a 10' wide green strip, and ultimately eliminate the diagonal parking in the Carriageway with a landscaped buffer in the future.

We have agreed to build the wider sidewalk as part of the JLR building construction, configured to easily add the green strip adjacent. The Herb Chambers Companies will cooperate with this work when it does happen.





1188 Commonwealth Avenue, Boston

Comment: "One big issue, you have nearly recreated the existing footprint. You have the opportunity to build more street frontage. Push the parking to the rear and claim the whole front. Articulate (the garage entry) if important. Even though this is not residential, can it be scaled here."





The parking to the east of the building is for Sales customers. This layout also allows for easy drive-in access for Service customers. These are the primary entrances to the dealership for Sales and Service.


















Sidewalk view looking west with 10' wide sidewalk



Sidewalk view looking west with 10' wide sidewalk and 10' wide grass strip

1188 Commonwealth Avenue, Boston



Aerial view looking west

1188 Commonwealth Avenue, Boston



Aerial view looking east







1188 Commonwealth Avenue, Boston

#### **BUILDING FACTS:**

<b>EXISTING</b>	<b>BUILI</b>	DING
-----------------	--------------	------

PARTIAL BASEMENT	8,285 S.F.
GROUND FLOOR	52,504 S.F.
EXISTING BUILDING AREA TOTAL	60,789 S.F.

#### **PROPOSED BUILDING**

GROUND FLOOR	47,248 S.F.
SECOND FLOOR	47,582 S.F.
THIRD FLOOR	49,190 S.F.
FOURTH FLOOR	48,301 S.F.
NEW BUILDING AREA TOTAL	192,321 S.F.

#### PARKING / STORAGE

•	
EXTERIOR SITE	58 SPACES
GROUND FLOOR DISPLAY	30 SPACES
SECOND FLOOR DISPLAY	23 SPACES
SECOND FLOOR STORAGE	106 SPACES
THIRD FLOOR STORAGE	153 SPACES
FOURTH FLOOR STORAGE	167 SPACES
TOTAL PARKING	537 SPACES